11:04:40

TE REPORT

PAGE 1

SITE NO: 104

SITE NAME: Columbia Steel/Joslyn Sludge Pond

ALIASES: Columbia Steel Casting Co., Inc.

SITE ADDRESS:

COUNTY: MULT STATUS: U

REGION: NW

TYPE: 3

10425 N. Bloss Avenue

Portland, OR 97203

DEQ CONTACT:

Take Columbia Blvd west of I-5 to Macrum Ave. Turn right and go approximately 5 blocks.

SITE CONTACTS:

SIC CODES: 2491 3532

Unknown

CERCLIS ORD#:

DEQ PROGRAMS: None Listed

CONFIRMED RELEASE?

YES

EVIDENCE VERIFIED?

YES

ON INVENTORY?

NO

SPILL? COMPLAINT? NO

NO

PRIOR VISIT?

30

SOME REMEDIAL ACTIONS ADJACENT PROPERTY?

ÑO NO

SIZE:

27.6

TNSHP: 1N

RANGE: 1E

SECT: 06

TAX LOTS: 7,118,122

*** FACILITY INFORMATION ***

FACILITY DESCRIPTION:

Steel casting / Joslyn - Pole treating operation Public/private not indicated

WASTE MGMNT UNIT

QTY

COMMENTS

None Listed

*** HAZARDOUS SUBSTANCES/WASTE TYPES ***

possible oil and creosote

01/23/89

11:04:52

TE REPORT

PAGE 2

SITE NO: 104

SITE NAME: Columbia Steel/Joslyn Sludge Pond

*** CONTAMINATION INFORMATION ***

A storm drain discharging to a pond located on private property was observed discharging an oily chemical substance. Follow-up investigation found small amounts of oil and creosote-like materials flowing from the drain. Flow was intermittent and not immediately discovered. Subsequent investigation indicates the presence of an abandoned wood treating sludge pond adjacent to the drain.

*** OTHER INFORMATION ***

Regional investigation indicates the presence of an abandoned wood treating sludge pond.

*** POTENUIAL RESPONSIBLE PARTIES ***

PRP NO. 1 PRP NAME: Columbia Steel Casting Co., Inc.

PHONE:

AFFILIATION: Legal Owner

STATUS: Current

Columbia Metal Casting Co., Inc.

P.O. Box 03095

Portland, OR 97203

PRP NO. 2

PRP NAME: Joslyn Manufacturing PHONE:

and the second of the control of the second of the second

AFFILIATION: Generator

STATUS: Current

Joslyn Manufacturing

*** INFORMATION AND DATA SOURCES ***

INFORMATION REVIEWED:

Correspondence from Owner or Operator

DATA SOURCES:

Abandoned Haz Waste Site notebook

01/23/89 11:05:02

TE REPORT

PAGE 3

SITE NO: 104

SITE NAME: Columbia Steel/Joslyn Sludge Pond

*** HAZARDOUS SUBSTANCES ***

SUBSTANCE NAME: pentachlorophenol

DATE RELEASED: Unknown QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC: Groundwater 8,300 ppb

Soil 2,100 ppm

possible groundwater contamination

DATA SOURCES: Abandoned Haz Waste Site Notebook

SUBSTANCE NAME: toluene

DATE RELEASED:

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC: Groundwater 440 ppb

Soil

183 ppm

SUBSTANCE NAME: napthalene

DATE RELEASED:

QTY RELEASED: Unknown

MEDIA/LEVEL OF CONC: Groundwater 12,000 ppb

Soil

6.6 ppm

01/23/89

11:05:15

FE REPORT

PAGE

SITE NO: 104

SITE NAME: Columbia Steel/Joslyn Sludge Pond

*** MANNER OF RELEASE ***

Abandoned

*** STATUS OF REMOVAL OR REMEDIAL ACTION ***

Columbia Steel has hired consultants to acess the problem.

REMEDIAL ACTION CODES ASSIGNED FOR LEGISLATIVE REPORT:

DEQ Oversight of or Technical Assistance to Responsible Party Investigation, Cleanup, RPIC

PREPARED BY: Michael Zollitsch

ORIGINATION DATE: 03/29/88

LAST MODIFIED BY: Alice Larsen

MODIFICATION DATE: 12/30/88

LAST UPDATED: 12/30/88 14:25:32